

STATISTICAL COMPARISON

NOVEMBER	2019	2020	2020 YTD
Number of Meters	3,865	3,902	
Total Revenue	\$929,777	\$490,685	\$9,652,655
Cost of Power	\$519,651	\$446,806	\$5,759,519
Total Cost of Service	\$799,279	\$765,304	\$9,189,665
kWhs Purchased	8,811,096	7,464,819	89,553,974
kWhs Sold	8,328,560	7,130,050	85,621,408
Line Loss %	5.15%	4.13%	4.14%
Residential Average kWh	1,830	1,490	
Residential Average Bill	\$201	\$105	

BOARD MEETING HIGHLIGHTS

December 2020

The December board meeting was held on December 23, at 8am via Zoom. All board members were present. Others present were Attorney Sheila Woodward, General Manager Stephanie Horst, Office Manager Nicole Einrem, Operations Manager Ken Carda, and Communications/Marketing Coordinator Jaclyn Arens.


The board reviewed and approved:

- Minutes of the Previous Meeting
- New Members & Cancellations
- Capital Credits to Estates in the amount of \$5,876.66
- Closed Work Order Inventory totaling \$50,540.17

The board reviewed and approved reports:

- East River Cyber Security/IT Report
- Reports from staff members as to the activities in their departments.
 - Office: Monthly Financial Report, Check Register, Bill Credit Recommendations, 2020 Write Offs, and 2021 Operating Budget
 - Member Service/Communications Report
 - Operations Report
 - Safety Report
 - 2020 ERP Table Top Planning Drill
 - General Manager's Report
- Reports from board members
 - South Dakota Rural Electric
 - East River Electric Power Cooperative
 - Attorney Report
- 2020 Audit Eide Bailly Engagement
- Designate 2021 NRTC Voting Delegate
- Executive Session
- Next meeting date set for Wed., Jan. 20, at 8 am.

December Solar Stats



5 kW Solar array used by Bon Homme Yankton Electric since 2018

Energy Efficiency Tip of the Month

Use wool or rubber dryer balls in the clothes dryer to reduce drying time and static.

Wool dryer balls can also absorb extra moisture. These are an efficient alternative to dryer sheets, which can create buildup on the dryer's filter and reduce air circulation. If you prefer dryer sheets, scrub the filter once a month to remove buildup.

Source: www.energy.gov

